

WS 22

Double End Stripping Tool

Instruction Sheet

Warning! This tool should not be used on live electrical circuits. It is not protected against electrical shock! Always use OSHA/ANSI or other industry approved eye protection when using tools. This tool is not to be used for purposes other than intended. Read carefully and understand instructions before using this tool.



This tool is designed to end strip overhead and underground secondary (600v) cables.

1. Select the correct end strip bushing, according to cable size.
2. Place tool over cable end.
3. With other hand, grasp the cable and place thumb at the desired stripping length.
4. Rotate the tool around the cable, using a slight forward pressure, and continue to rotate tool until it reaches your thumb. Rotate the tool one or two more turns against your thumb. This will end cut the insulation. (Do not reverse turning direction)

Replacement Blade: Model CB22 (p/n 12302)

WARRANTY: RIPLEY warrants its products against defective materials and workmanship for a period of one year from date of shipment from the RIPLEY factory provided the product is utilized in accordance with instructions and specified ratings.



46 Nooks Hill Road
Cromwell, CT 06416
Phone: 800-528-8665
Int'l: (01) 860-635-2200
Fax: (01) 860-635-3631
E-mail: info@ripley-tools.com
Internet: www.ripley-tools.com



12324 rev2
12-01-12 ff