


# FTTX Drop End Prep Kit

Simplify field connector installation on flat drop fiber with these FTTX Drop End Prep Kits.

**Featuring a complete range of tools for rapid, measured jacket stripping, fiber stripping, loose tube scoring, strength member cutting, and both Kevlar® and fiberglass trimming, the FTTX Drop End Prep Kits contains everything a fiber installer needs to strip and prep flat drop fiber-to-the-home cables.**

Professional, hard-wearing, and featuring the most trusted, cutting-edge Miller® tools, these kits are essential for any fiber cable technician.

## FTTX Flat Drop End Prep



Kit contains	Part numbers	Dimensions
MB04-7000 for Jacket Strip	MA03-7039 1.35lb (612g)	Length: 10"
FTS for Loose Tube Score		Width: 4.5"
CFS-3 for Fiber Stripping		Depth: 3"
MA04-7001 Cutter for Strength Members		
KS-2 for Kevlar and fiberglass trimming		


For more information or to locate your nearest authorized Ripley® distributor, visit [www.ripley-tools.com](http://www.ripley-tools.com) or call **1 (800) 528-8665** to speak with a customer service representative.

## FTTX Flat Drop End Prep W/Toner Wire



Kit contains	Part numbers	Dimensions
MB03-7120 cable splitter for toner wire MB04-7000 for jacket strip FTS for loose tube score CFS-3 for fiber stripping MA04-7001 cutter for strength members KS-2 for Kevlar and fiberglass trimming	MA03-7046 1.65lb (748g)	Length: 10" Width: 4.5" Depth: 3"

## FTTX ULW Drop End Prep



Kit contains	Part numbers	Dimensions
MB04-7020 for ULW jacket strip FTS for loose tube score CFS-3 for fiber stripping MA04-7001 cutter for strength members KS-2 for Kevlar and fiberglass trimming	MA03-7043 1.35lb (612g)	Length: 10" Width: 4.5" Depth: 3"

For more information or to locate your nearest authorized Ripley® distributor, visit [www.ripley-tools.com](http://www.ripley-tools.com) or call **1 (800) 528-8665** to speak with a customer service representative.



**RIPLEY**  **LABS**

Invented in Ripley Labs