




MS02 Series




Prysmian FlexRibbon Separator 24F


Slices 24 fiber Prysimian FlexRibbon into 2 x 12F ribbons. This tool provides consistent, damage-free separation of FlexRibbon




Clean both sides of blade before slicing operation.




Carefully separate ribbons at load location. Load around and under blade edge. Do not break matrix.



Ensure ribbon is flat in groove with no overlapping fibers. Slide ribbon forwards/backwards to align with blade.



Close latch.



Apply gentle thumb pressure to add drag. Pull ribbon along arc towards blade edge to slice matrix. Slice 1 matrix node every 5 seconds or slower.

WARNING: This tool should not be used on live electrical circuits. It is not protect against electrical shock.

Always use OSHA/ANSI/CE or other industry approved eye protection when using tools. This tool is not to be used for purposes other than intended. Read carefully and understand instructions beofre using this tool.

For more information or to locate your nearest authorized Ripley® distributor, visit www.ripley-tools.com or call 1 (800) 528-8665 to speak with a customer service representative.



A proud member of the Hubbell family.